



State of Utah

DEPARTMENT OF ENVIRONMENTAL QUALITY DIVISION OF AIR QUALITY



4637 AIR

SS/u/c

Michael O. Leavitt
Governor
Dianne R. Nielson, Ph.D.
Executive Director
Ursula K. Trueman
Acting Director

150 North 1950 West
P.O. Box 144820
Salt Lake City, Utah 84114-4820
(801) 536-4000 Voice
(801) 536-4099 Fax
(801) 536-4414 T.D.D.

October 31, 1996

DAQC-1852-96

Dale Hansen
Thatcher Company
P.O. Box 27407
1905 West Fortune Road
Salt Lake City, Utah 84127

Dear Mr. Hansen:

Re: Thatcher Company - Protocol Review and Test Date Confirmation - Thatcher Company,
Impinjet SO2 Scrubber - Salt Lake County

A review of the emissions testing protocol received October 17, 1996, has been conducted and the protocol has been found to be unacceptable. Deficiencies were found in the protocol that need to be addressed as soon as possible. The deficiencies included: 1) no mention of means to monitor production rates, 2) no mention of production rate range, 3) no submittal date of report, 4) no name of responsible party from Thatcher Company, 5) no mention of an acceptable sample recovery area. In order to accept the pretest protocol, these deficiencies need to be corrected.

If you have any questions, please contact me at (801) 536-4028.

Sincerely,

Anthony DeArcos, Environmental Scientist
Division of Air Quality

AD:kh

cc: Salt Lake City/County Health Department
EPA Region VIII, Lee Hanley



Thatcher Chemical
49-035-00119